

  
**WELDAXIS System**  
User Manual



**TOL-O-MATIC, INC**  
*Excellence in Motion<sup>®</sup>*

© Copyright 2004 Tol-O-Matic, Incorporated.  
All rights reserved. Axidyne and Tol-O-Matic  
are registered trademarks of Tol-O-Matic Incorporated.  
All other products or brand names  
are trademarks of their respective holders.

# Contents

---

<b>1: Health and Safety Regulations</b> .....	<b>1-1</b>
1.1 General .....	1-1
1.2 Warning for hot surfaces .....	1-1
1.3 Modifications to equipment .....	1-1
1.4 Requirements regarding personnel .....	1-2
1.5 Packing, transport and unpacking .....	1-2
1.6 Risk area and personnel .....	1-2
1.7 Repair and maintenance .....	1-2
<b>2: General</b> .....	<b>2-1</b>
2.1 Intended use .....	2-1
2.1.1 Weld Axis component system .....	2-1
2.1.2 Weld Axis panel system .....	2-2
2.2 Identification .....	2-4
2.2.1 Actuator identification .....	2-4
2.2.2 Weld Axis component system .....	2-5
2.2.3 Weld Axis panel system .....	2-5
2.3 Manufacturer .....	2-6
<b>3: Function Description</b> .....	<b>3-1</b>
3.1 Weld Axis controls .....	3-1
3.2 Hand-held teach pendant .....	3-2
3.3 Single board computer .....	3-2
3.4 Axiom Plus (PV) .....	3-2
<b>4: Installation</b> .....	<b>4-1</b>
4.1 Installing the weld actuator .....	4-1
4.2 Installing the weld component system .....	4-1
4.3 Installing the Weld Axis panel system .....	4-1
4.4 Power required for Weld Axis .....	4-1
4.5 Interface to master controller .....	4-2
4.6 Setup .....	4-2
4.6.1 General .....	4-2
4.6.2 Inspection of mechanical travel limits .....	4-2
4.6.3 Axiom Plus controller setup .....	4-3
4.6.4 Axiom Plus PLC program .....	4-4
4.6.5 Axiom Plus sequential program .....	4-6
4.6.6 Weld Axis teach pendant / single-board computer .....	4-6
4.6.6.1 Menu Structure .....	4-6
4.6.6.2 Setup weld data .....	4-8
<b>5: Repair and Maintenance</b> .....	<b>5-1</b>
5.1 Weld actuator .....	5-1
5.2 Weld Axis control panel .....	5-1
5.2.1 Testing of the actuator weld force .....	5-1
5.2.2 Changing the caps .....	5-1

---

# C O N T E N T S

<b>6: Appendix .....</b>	<b>6-1</b>
6.1 Motor specifications.....	6-1
6.1.1 HT12 .....	6-1
6.1.2 HT23 .....	6-1
6.2 Connector pinout .....	6-2
6.2.1 Motor armature.....	6-2
6.2.2 Motor encoder .....	6-2
6.2.3 Teach pendant.....	6-3
6.3 Weld Axis base system wiring diagram .....	6-4
6.4 Weld Axis panel system wiring diagram .....	6-5
6.5 Axiom Plus standard PLC program .....	6-9
6.6 Axiom Plus standard sequential program .....	6-19

## LIST OF FIGURES

<b>Figure</b>	<b>Description</b>	
2.1	Weld Axis component system .....	2-2
2.2	Weld Axis panel system.....	2-3
2.3	HT series weld actuator.....	2-4
2.4	Actuator identification label.....	2-4
2.5	Control panel label.....	2-5
3.1	Example Weld Axis control panel.....	3-1
3.2	Hand-held teach pendant .....	3-2
4.1	Manual operation of HT series actuator .....	4-2
4.2	Axiom Plus setup and configuration screen .....	4-3
4.3	Axiom Plus register precision configuration screen.....	4-4
4.4	I/O table .....	4-5
4.5	Teach pendant menu structure.....	4-7
6.1	Pinout of motor armature connection .....	6-2
6.2	Pinout of motor encoder connection .....	6-2
6.3	Pinout of teach pendant connection.....	6-3
6.4	Base system wiring.....	6-4
6.5	Weld Axis HT12 3-phase wiring diagram (1 of 4) .....	6-5
6.6	Weld Axis HT12 3-phase wiring diagram (2 of 4) .....	6-6
6.7	Weld Axis HT12 3-phase wiring diagram (3 of 4) .....	6-7
6.8	Weld Axis HT12 3-phase wiring diagram (4 of 4) .....	6-8

## 1.1 General

Read completely through the applicable sections of the manual before the equipment/unit is unpacked, installed or operated. Pay careful attention to all of the dangers, warnings, cautions and notes stated in this manual.

Serious injury to persons or damage to the equipment may result if the information contained in this manual is not followed.

Items that are specifically marked **DANGER!**, **WARNING!**, **CAUTION!**, or **NOTE!**, are arranged in a hierarchical system and have the following meaning:



**DANGER!** Indicates a very hazardous situation which, if not avoided, could result in death or serious injury. This signal word is limited to the most extreme situations.



**WARNING!** Indicates a potentially hazardous situation which, if not avoided, could result in death or serious injury.



**CAUTION!** Indicates a potentially hazardous situation which, if not avoided, this situation may result in property damage or minor or moderate injury.



**NOTE!** This Information requires special attention.

## 1.2 Warning for Hot Surfaces



**WARNING!** Normal operating temperature of weld actuator can reach 175 Degrees F.

## 1.3 Modifications to the equipment



**WARNING!** The manufacturer takes no responsibility whatsoever if the equipment is modified or if the equipment is used in any way not intended at the time of delivery. Unauthorized modifications or changes to the equipment are strictly forbidden.

## ***1.4 Requirements regarding Personnel***

 **NOTE!** All personnel must be completely informed regarding all safety regulations and the function of the equipment.

## ***1.5 Packing, Transport and Unpacking***

 **NOTE!** Anchor and secure actuator in such a way as to prevent damage during transport. Also make sure the actuator is clean and dry and protected from moisture.

## ***1.6 Risk Area and Personnel***

 **WARNING!** When Weld Axis components are installed in a weld gun, pinch points are generated that exert dangerous forces capable of severe bodily injury. The risk area surrounding the weld actuator must either be enclosed or clearly marked including display signage in accordance with all applicable national and international legal requirements for welding actuators. The risk area must be protected by a safety system that stops the equipment if anyone enters the risk area. Personnel who enter the risk area must be authorized, trained and qualified for the different tasks inside the risk area.

## ***1.7 Repair and Maintenance***

All supply media must be shut OFF (electricity) before any work is begun on any equipment that is associated with the welding gun application.

## **2.1 Intended Use**

The Weld Axis System is intended to be used as a servo retrofit to an existing pneumatic actuator on a spot welding gun where inputs from a primary controller such as a robot, weld controller, or PLC point to a weld schedule(s) and triggers the servo actuator to close. The Weld Axis System is also intended to be a cost-effective alternative to the 7th axis of robots, as well as in fixture applications where no other motion control exists.

The Weld Axis functions as a motion controller, a motor driver, and a convenient setup and calibration tool for servo welding. Setup and calibration is performed using a hand-held teach pendant. Setup information is retained within a removable flash card on the computer and not in the teach pendant, allowing a single teach pendant to be used with multiple systems.

The Weld Axis System can be supplied as a component system for convenient integration into existing panels or as a complete system in its own enclosure

### **2.1.1 WELD AXIS COMPONENT SYSTEM**


---

The Weld Axis Component System includes the following:

- Servo weld actuator
- Controller/drive (Axiom Plus PV20 or PV30)
- Single board computer
- Hand-held teach pendant (one may be used for multiple systems)
- 24 VDC Power supply
- Cables and Connectors
- Schematics/wiring diagrams

Components are integrated into the users panel as shown in Figure 2.1





**Figure 2.2 – Weld Axis Panel System**

The following options are available:


- Devicenet interface.
- Thirty meter motor and encoder cables
- Drive isolation transform

**WARNING!** Before installation and commissioning of the equipment, this manual and all accompanying manufacturer documents and manuals **MUST** be completely read by the concerned personnel. All warning texts must be given special attention.

## 2.2 Identification


### 2.2.1 ACTUATOR IDENTIFICATION

Figure 2.3 shows an example of a standard Tol-O-Matic, Inc. HT series actuator.



*Figure 2.3 – HT series weld actuator*

Figure 2.4 shows a sample label that is affixed to the actuator. Do not remove the actuator identification label and do not make it unreadable!



*Figure 2.4 – Actuator identification label*

---

### **2.2.2 WELD AXIS COMPONENT SYSTEM**

The Weld Axis Component system consists of the following parts:


DESCRIPTION	QUANTITY
PWR SUP,24VDC,50W	1
Weld Axis SBC WITH	1
ASSY,CABLE W/CONN,SBC	1
CABLE,RS232	1
CABLE,AXIOM PLUS/SBC	1
AXIOM PLUS,PV20,W/SFT	1
CABLE ASSY,15M,POWER	1
CABLE ASSY,15M,ENCODER	1

The following table shows the proper Axiom Plus(PV) to be use with the various size weld actuators:

Actuator Model #	Axiom Plus Model #
HT7	PV10
HT12	PV20
HT23	PV30
SWxx	PV30

### **2.2.3 WELD AXIS PANEL SYSTEM**

In the Weld Axis panel system manufactured by Tol-O-Matic, Inc. there will be a label affixed to the inside of the control panel door (see figure 2.5).



**Figure 2.5 – Control Panel Label**


## **2.3 Manufacturer**

**Tol-O-Matic, Inc.**  
3800 County Road 116  
Hamel, MN 55340  
USA  
763-478-8000

Perform repairs, maintenance and inspections before storing the actuator to ensure that the gun is in good working order. Make sure the actuator is placed in a suitable storage position to prevent damage to the connectors and electronics. Store the control cabinet in a clean dry place with humidity between 5% and 95%, non-condensing. Make sure the temperature is between -4° to 158° F (-20° to 70° C).

## 3.1 Weld Axis Controls

The Weld Axis controls are used to control the position and force of the weld actuator based on the inputs from a master controller. The I/O structure is designed to mimic a pneumatic system allowing for easy retrofitting into an existing application. Figure 3-1 shows an example Weld Axis panel system.



*Figure 3.1 – Example Weld Axis control panel*



**WARNING!** High voltage may be present on the terminals of the unit. Remove power and disconnect the power cable before making or removing any connection.

### **3.2 Hand-held Teach Pendant**

The hand-held teach pendant is used as the operator interface. The operator enters the setup and welding parameters and the values are transferred to the Single Board Computer/removable flash card. The same hand-held teach pendant can be used with multiple systems. If an installation has multiple Weld Axis systems only one hand-held teach pendant would be needed.



*Figure 3.2 – Hand-held teach pendant*

### **3.3 Single Board Computer**

The single board computer gets user data from the hand held teach pendant and converts the user data into the register values that the Axiom Plus requires. The single board computer can backup the data entered by the user and the Axiom Plus program to a removable flash memory card.

### **3.4 AxiomPlus (PV)**

The Axiom Plus controller/drive provides the power to run the motor and the logic to respond to the interface signals. The Axiom Plus runs PLC and Sequential programs to produce the desired motion and weld forces. For more information on the Axiom Plus see the Axiom Plus Users Manual (3600-4628).

## 4.1 Installing the Weld Actuator

Please refer to your weld gun documentation for mechanical installation

## 4.2 Installing the Weld Axis Component System

The Weld Axis Component System includes the necessary parts to integrate a Weld Axis system into an existing enclosure or customer designed control panel. A wiring diagram is included in appendix 6.3. The heat dissipation of the Axiom Plus for cabinet sizing is:

Actuator Model	Axiom Plus Model	Heat dissipation
HT7	PV10	28 Watts
HT12	PV20	47 Watts
HT23	PV30	65 Watts
SWxx	PV30	65 Watts

## 4.3 Installing the Weld Axis Control System

Weld Axis enclosures supplied by Tol-O-Matic, Inc. are NEMA 12 rated and should be mounted in a location where the environment does not exceed the specifications of the NEMA 12 rating.

## 4.4 Power required for the Weld Axis

Tol-O-Matic recommends the Weld Axis system be used with three phase 208-230 VAC power. The table below lists the required amperage. If a step down transformer is required, it is recommended a drive isolation type transformer with a delta primary and a wye secondary winding be used.

	HT7 (PV10)	HT12 (PV20)	HT23 & SWxx (PV30)
Maximum Input Current Single Phase	12.5 A (rms)	25 A (rms)	37.5 A (rms)
Maximum Input Current Three Phase	7.5 A (rms)	15 A (rms)	22.5 A (rms)
Input Voltage (Single or Three Phase)	190VAC – 250VAC	190VAC – 250VAC	190VAC – 250VAC
Peak Inrush Current	65 A	160 A	160 A
Input Frequency	47 Hz – 63 Hz	47 Hz – 63 Hz	47 Hz – 63 Hz

## 4.5 Interface to master controller

The Weld Axis is designed to operate as a slave to a master controller. The interface can be customized to work with an existing master controller.

## 4.6 Setup

### 4.6.1 GENERAL

Before commissioning the weld actuator, there are certain inspections and settings that must be carried out. Also after maintenance activities, the gun must be inspected before it is returned to service.

### 4.6.2 INSPECTION OF MECHANICAL TRAVEL LIMITS.

The mechanical travel limits of the actuator must be verified to ensure the actuator will not reach an internal hard limit during normal operation. Turn the controller power off. With the actuator installed on a weld gun, manually rotate the servo gun gear or pull the gun arms apart, extending the tube until the weld gun tips are closed and record the distance the rod is extended (d1). Remove one arm and manually rotate the servo gun gear or push the gun arms together, until the actuator reaches its end of travel and record the distance the rod is extended (d2). The difference between the two measurements, minus the gun deflection (d3) should be greater than 5 mm ( $d2 - d1 - d3 \geq 5\text{mm}$ ).





Figure 4.1 – Manual operation of HT series actuator

### 4.6.3 AXIOM PLUS CONTROLLER SETUP


The setup of the Axiom Plus only needs to be verified during initial installation. All settings are backed up on the Single Board Computer (SBC) flash memory card. Using the Axiom Plus programming software running on a PC the following selections are verified:

1. Select the correct indexer model being used.
2. Select the motor winding being used. This information is indicated on the actuator label
3. Select the register precision. See figure 4.3 for settings.

After the settings have been made, they should be downloaded to the Axiom Plus using the “Download Parm’s to indexer” button.



*Figure 4.2 – Axiom Plus Setup and Configuration Screen*



*Figure 4.3 – Axiom Plus Register Precision Configuration Screen*

#### **4.6.4 AXIOM PLUS PLC PROGRAM**

The Axiom Plus PLC program needs to be set up to match the I/O requirements and assignment of the supervisory controller. A listing of the Axiom Plus standard PLC program is included in the appendix 6.5. The first 12 rungs of the PLC program are used to assign physical inputs to local flags and the next 3 rungs assign internal flags to physical outputs. Although physical inputs can be reassigned to any of the internal flags, it is recommended that the default assignment be used. The PLC program contains the logic to determine what routine that the sequential program will run based on the inputs from the master controller. The following table is a list of the I/O in the standard Weld Axis PLC program.

Physical Input	Internal Flag	Description
IN001	LF001	"Binary 1" - Binary 1-8 input sequence is used to select the weld schedule 1-15. The binary sequence has to be set before the close gun command is received for the master controller.
IN002	LF002	"Binary 2"
IN003	LF003	"Binary 4"
IN004	LF004	"Binary 8"
IN005	LF006	"Backup 1" - Backup 1-4 input sequence is used to select the open positions 0-7 based on the
IN006	LF007	"Backup 2"
IN007	LF008	"Backup 4"
IN008		Spare
IN009	LF005	"Close" - When input is on the actuator will close at the position and pressure set with binary 1,2,3,4 and remain closed until the input is removed.
IN010	LF019	"ClearErr" - Clears the position error output.
IN011	LF012	"CheckCap" - Used to check the wear of the caps. When this input is on and the close signal is received the actuator will close at a slow speed until the tips touch. If the caps are worn past the value entered in the TP then the "CapWore" output will be activated.
IN012	LF017	"ManNewCP" - Used to indicate that new caps have been installed. When this input is on and the close signal is received the actuator will close at a slow speed until the tips touch. This position will become the new cap value.
IN013		spare
IN014		spare
IN015	LF010	"No Estop" - When input is on drive stage will be enabled
OUT1	STP021	"Sig Weld" - Ready to weld signal
OUT2	IS002	"Fault" – The drive is faulted.
OUT3	STP018	"Opened" – Actuator is at an open position.
OUT 4	LF018	"PosError" - When using either the "close position" or the "dynamic" position checks, this output will turn on if the actuator stops during a weld move in an invalid position.
OUT 5	STP012	"CapWore" - Indicated that the caps are worn beyond the service limit entered in the TP. The output will stay on until another cap check is done and the caps are with the wear limit.
OUT 6		spare
OUT 7		spare
OUT 8		spare

**Figure 4.4 – I/O Table**

---

#### **4.6.5 AXIOM PLUS SEQUENTIAL PROGRAM**

The sequential program consists of a main loop that calls the subroutines associated with each weld schedule and open position. The PLC program sets internal flags that are read by the sequential program. In most applications the Axiom Plus sequential program will not need to be modified. A listing of the sequential is included in appendix 6.6.

#### **4.6.6 WELD AXIS TEACH PENDANT/SINGLE BOARD COMPUTER**

---

##### **4.6.6.1 Menu Structure**

The Weld Axis teach pendant and single board computer are used to provide the user with a simple way to interact with the Axiom Plus controller. All the setup and troubleshooting of the system is done from the teach pendant.

Figure 4-5 shows the teach pendant menu structure with a description of each item.

<b>SETUP</b>	<b>Force units</b>		Select between imperial and metric units	
	<b>Length units</b>		Select between imperial and metric units	
	<b>Gun Ratio</b>		Enter the ratio of actuator travel to tip travel	
	<b>Force Capacity of Gun</b>		Enter the maximum force the weld gun can produce.	
	<b>Define Limits</b>		The Define Limits is used to define the travel limits of the actuator. To determine the limits remove the tips from the weld gun and choose this command then give the gun close signal from the external controller. The gun will close at a low speed until the end of travel is reached. When the end of travel is reached the position will be recorded and that this position minus 0.05 inches will become the forward position limit. If the forward position limit is reached during normal operation a FL1 will be displayed on the Axiom Plus front panel LED.	
	<b>Position Checks</b>	None	No position checks are done at the weld position	
		Close Position	When Close Position is selected a valid weld position window is created. Before the ready to weld signal is given the tips must be between the deceleration point and the tips closed position plus the cap wear value. If the current position is outside the valid window the "poserror" output is turned on and the ready to weld signal will not be given.	
		Dynamic	When Dynamic is selected a valid weld position window is created. Before the ready to weld signal is given the tips must be between the deceleration point and the last valid weld position plus the cap missing value entered as part of the dynamic position check setup. If the current position is outside the valid window, the "poserror" output is turned on and the ready to weld signal will not be given.	
<b>Start Calibration</b>		Start calibration is used to set the starting value of motor torque used during the calibration process. The default value is 5% of motor torque. If the actuator will not move at 5% during calibration, raise the value in Start Calibration until the first calibration move is successful.		
<b>Decel Point Offset</b>		Decel Point Offset is the distance before the tips touch the part, where the actuator starts to decelerate to the soft touch speed. The default value is 0.125". A larger value may be required if the tips are not at soft touch speed before impacting the workpiece.		
<b>CALIBRATION</b>			Calibration is the process of defining the relationship between the drive output current and the weld force. When the calibration option is chosen from the menu, the teach pendant will ask the operator to close the tips on a force gage and enter the resulting force at ten different levels of drive current. When a force is entered in the weld schedule, the value of drive current is interpolated from the values entered during calibration. During the calibration process the positions are recorded at the different force levels to create a force vs. deflection curve. This curve is used when doing position checks and cap wear monitoring.	
<b>DEFINE CLOSE</b>			Used to define the tips closed position of the weld gun. The Define Close is a two stage process. The first move is done at minimum torque and is used to determine the soft touch decel point. The second stage is done at the maximum gun force and is used to calculate values for positioning checking and cup wear.	
<b>WELD SCHEDULE</b>	1-8		The fifteen weld schedules are used to enter the weld force and the thickness of the material being welded. The thickness is used along with the gun closed location to calculate the decel point for the soft touch feature. A text field is included to allow for a comment to be entered for each weld schedule. The weld schedule number corresponds to the binary sequence set by four. The second page of the weld schedules is accessed by pressing the ? key.	
	9-15			
<b>OPEN POSITION</b>	0-7		The eight open positions are used to define the distance between the tips when the weld gun is in the open position.	
<b>DIAGNOSTICS</b>	<b>Current Drive Status</b>		Shows the drive status code and description along with the current position of the actuator.	
	<b>Drive History</b>		Shows the last 13 drive status changes including the status code and the time/date.	
	<b>Reset Drive</b>		Used to reset a non-fatal fault from the teach pendant	
	<b>Reset Parameters</b>		Resets all the setup parameters entered from the teach pendant.	
	<b>Change Date/Time</b>		Set the current date and time for use in the drive history.	
	<b>Data Storage</b>	Backup Axiom Plus		This option will backup both the Axiom Plus program and configurations to the removable flash memory card. This operation will take about 5 minutes to complete
		Restore Axiom Plus		This option will restore the Axiom Plus program and configurations that was backup on the removable flash card. This operation will take about 5 minutes to complete.
		Manually backup weld data		This option will backup all the data entered into the teach pendant.
		Restore manual weld data		This option will restore the teach pendant settings backed up using the "Manually backup weld data option"
Restore autosaved weld data		This option will restore the teach pendant settings that are automatically saved every time the teach pendant goes to the main menu.		
<b>I/O Status</b>			Shows the status of the Axiom Plus inputs, outputs and the current position.	

**Figure 4.5 – Teach pendant menu structure**

#### **4.6.6.2 Setup Weld Data**

When setting up a new Weld Axis system, the following steps should be completed in order.

- 1) **Enter the system of units for the force.**
- 2) **Enter the system of units for distance.**
- 3) **Enter the gun ratio.** The ratio is the actuator travel divided by the tip travel.
- 4) **Enter the mechanical force limit for the weld gun.**
- 5) **Define the position limits.** The actuator limit is the forward travel limit of the actuator. The limit is found by removing the tips from the weld gun and choosing the define limits option from the setup menu and then giving the gun close signal from the external controller. The gun will close at a low speed until the end of travel is reached. The end of travel position is then loaded into the Axiom Plus as the forward position limit.
- 6) **Calibrate the actuator.** Calibration is needed to create a relationship between the motor armature current and the force output of the actuator. The user will use a force gage to measure the force between the tips at ten motor current levels. On the teach pendant select the calibration option. The screen will indicate the percentage torque being used and will wait for the user to enter the force value measured. To measure the force place the gage between the tips and turn on the close gun command from the master controller. The gun will close at a slow speed until the tips contact the force gage. Once the force has been entered it will progress to the next current level until the calibration is complete. If the actuator fails to move at the lower levels of motor torque, enter zero for the force. When the calibration is complete, change the "Start Calibration Value" in the setup menu to the first value where the actuator closed correctly.
- 7) **Define the tips closed position.** This position is needed to calculate the deceleration point for the soft touch feature. Use the define close position option on the teach pendant, the system will wait until the close gun command is turned on from

the master controller. The gun will then close at a slow speed at minimum motor torque until the tips are closed. The actuator will open slightly and close again at gun capacity.

- 8) **Setup the desired weld schedule.** The weld schedule is what specifies the force for the weld and the stackup of the material being welded. The stackup and the tips closed position are used to determine the position were the system goes to soft touch speed. There are 15 possible weld schedules possible. The weld schedule is displayed in two pages, the second page is displayed by pressing the down arrow button. To modify the value for a weld schedule enter the number of the weld schedule, another page is displayed allowing the user to enter a description, the weld force and the max stackup.
  
- 9) **Determine the desired open position.** The open position is defined as the distance between the weld gun tips. There are eight possible open positions. To modify an open position number to be modified and the choose the comment or the open distance.

## 4 : I N S T A L L A T I O N

---

### ***NOTES:***

## **5.1 Weld Actuator**

 **NOTE!** Before starting any maintenance activities, make sure that the supply voltage is shut OFF.

No lubrication is required during the service life of the weld actuator.

Disassembly of the weld actuator is not recommended. Weld Actuators should be returned to Tol-O-Matic for evaluation and repair. Contact the weldgun manufacturer for instructions on how to return the weld actuator for evaluation.

## **5.2 Weld Axis Control Panel**

---

### **5.2.1 TESTING OF THE ACTUATOR WELD FORCE**

When the Weld Axis starts to close the gun, it does not limit the motor torque until it transitions to the soft touch speed. When checking weld force, be sure to select a weld schedule that has a stackup larger than the force gage being used. If the force measured is not within specifications for the force set in the weld schedule, the system should be re-calibrated.

---

### **5.2.2 CHANGING THE CAPS**

When changing the caps, the tips closed position will need to be redefined if the new caps are a different style or if the close position has been redefined with used caps. If these conditions do not apply, the new caps can be installed without accessing the teach pendant.

### 5.2.3 FAULT CODES

---

## *Troubleshooting Guide*

Tol-O-Matic Axiom series drives are designed for ease of installation and years of trouble-free operation. If difficulties are encountered in the setup or in operation, this guide should prove useful in diagnosing and correcting the problem. If problems persist, please contact your Tol-O-Matic distributor for further assistance.

**Symptom/Fault Code:** Status display not lit.

**Possible Causes:** No ac power; internal malfunction.

**Possible Solutions:** Verify ac power and connections; call your Tol-O-Matic distributor.

**Symptom/Fault Code:** Digital I/O not working correctly.

**Possible Causes:** No 5-25Vdc power.

**Possible Solutions:** Verify correct connection.

**Symptom/Fault Code:** F01 - Power selection switch fault.

**Possible Causes:** Line-power selection switch set incorrectly.

**Possible Solutions:** Set to “115 V” for 115 Vac operation or “230 V” for 208 Vac or 230 Vac operation.

**Symptom/Fault Code:** F02 - Bridge hardware fault.

**Possible Causes:** Motor lead short circuit; bus over-voltage; drive’s output bridge damaged.

**Possible Solutions:** Check motor cables and motor for shorts; connect internal or external regen resistor; call your Tol-O-Matic distributor.

**Symptom/Fault Code:** F03 - Current feedback fault.

**Possible Causes:** Possible open winding; current feedback circuitry not functioning correctly.

**Possible Solutions:** Check motor cable wiring and motor windings; call your Tol-O-Matic distributor.

**Symptom/Fault Code:** F04 - Current regulation fault.

**Possible Causes:** Drive current regulation out of tolerance; current feedback in “saturation” for 1 second.

**Possible Solutions:** Check motor cables and motor windings; verify that torque/speed requirement not greater than motor/drive capability.

- 
- Symptom/Fault Code:** F05 - Drive over-temperature fault.  
**Possible Causes:** Drive heat sink over 90° C.  
**Possible Solutions:** Ambient temp above 50° C.; need external regen pack.
- Symptom/Fault Code:** F06 - Motor over-temperature fault.  
**Possible Causes:** Motor thermostat tripped.  
**Possible Solutions:** Inadequate motor cooling; motor rating exceeded.
- Symptom/Fault Code:** F51 - Phasing fault.  
**Possible Causes:** Initial phase estimation routine not executed successfully.  
**Possible Solutions:** Check encoder and motor wiring; increase phasing torque.
- Symptom/Fault Code:** F52 - Drive over-current fault.  
**Possible Causes:** Inverse time trip calculated based on the drive's peak and continuous rating exceeded.  
**Possible Solutions:** Verify sizing requirements; check tuning; check for mechanical problems in system.
- Symptom/Fault Code:** F53 - Motor over-current fault.  
**Possible Causes:**  $I^2 \cdot \text{time}$  protection based on the motor's peak and continuous rating exceeded.  
**Possible Solutions:** Verify sizing requirements; check for mechanical problems in system.
- Symptom/Fault Code:** F54 - Bus under-voltage fault.  
**Possible Causes:** Bus voltage falls below low-limit.  
**Possible Solutions:** Check line voltage under load (must be at least 90 Vac).
- Symptom/Fault Code:** F55 - Maximum following-error fault.  
**Possible Causes:** Maximum position following error reached.  
**Possible Solutions:** Verify correct maximum following error setting; check tuning; check for mechanical problems in system.
- Symptom/Fault Code:** F56 - Velocity regulation fault.  
**Possible Causes:** Velocity regulation out of tolerance.  
**Possible Solutions:** Check tuning; check for mechanical problems in system.
- Symptom/Fault Code:** F57 - Serial communication fault.  
**Possible Causes:** Communication cable not connected.  
**Possible Solutions:** Check communication cable connections.
-

.....

.....

## 6.1 Motor Specifications

### 6.1.1 HT12

<i>Continuous Stall Torque:</i>	3.4 N-m
<i>Peak Stall Torque:</i>	16.9 N-m
<i>Thermal Resistance:</i>	0.58 celsius/watt
<i>Stall Current:</i>	6.13 A RMS
<i>Peak Current:</i>	30.7 A RMS
<i>Number of Poles:</i>	4
<i>Kt:</i>	0.58 N-m/Amp per phase RMS
<i>Ke:</i>	0.332 V/rad/s L-L RMS
<i>Resistance @ 25 C:</i>	2.0 ohms L-L
<i>Stator Inductance:</i>	6.1 mH L-L
<i>Maximum Bus Voltage:</i>	325 Vdc
<i>Rated Speed @ Maximum Voltage:</i>	4500 RPM
<i>Demagnetization Current:</i>	39 Amps

Thermal sensor will shut down the motor at 311 degrees F. However the motor should not perform a duty cycle that repeatedly generate motor temperatures above 175 degrees F, or premature bearing failure will result.

### 6.1.2 HT23

<i>Continuous Stall Torque:</i>	5.0 Nm
<i>Peak Stall Torque:</i>	24.9 Nm
<i>Thermal Resistance:</i>	0.56 celsius/watt
<i>Stall Current:</i>	7.55 A RMS
<i>Peak Current:</i>	37.8 A RMS
<i>Number of Poles:</i>	4
<i>Kt:</i>	0.69 Nm/amp per phase RMS
<i>Ke:</i>	0.396 V/rad/s L-L RMS
<i>Resistance @ 25 C:</i>	1.4 ohms L-L
<i>Stator Inductance:</i>	5.1 mH L-L
<i>Maximum Bus Voltage:</i>	325 Vdc
<i>Rated Speed @ Maximum Voltage:</i>	4500 RPM
<i>Demagnetization Current:</i>	45 Amps

Thermal sensor will shut down the motor at 311 degrees F. However the motor should not perform a duty cycle that repeatedly generate motor temperatures above 175 degrees F, or premature bearing failure will result.

## 6.2 Connector Pinout

### 6.2.1 MOTOR ARMATURE




Figure 6.1 – Pinout of motor armature connection

### 6.2.2 MOTOR ENCODER





Figure 6.2: Pinout of motor encoder connection

### 6.2.3 TEACH PENDANT

#### HAND-HELD CONNECTOR PINOUT

PIN	Function
A	Transmit TXD2
B	+24 Vdc
C	0 Vdc
D	Receive RXD2
E	Input #1 on SBCF
F	0 Vdc
G	
H	




*Figure 6.3 – Pinout of teach pendant connection*



### 6.4 Weld Axis Panel System wiring diagram

101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141




TOL-O-MATIC, INC. : WELD-AXIS HT12 3-PHASE DWG#3620-7104, REV 00, PAGE 1

Figure 6.5 – Weld Axis HT12 3-phase wiring diagram (1 of 4)

6 : APPENDIX


201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241



TOL-O-MATIC, INC: WELD-AXIS HT12 3-PHASE DWG# 3620-7104, PAGE 2

Figure 6.6 – Weld Axis HT12 3-phase wiring diagram (2 of 4)

301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341



TOL-O-MATIC, INC.: WELD-AXIS HT12 3-PHASE DWG# 3620-7104, PAGE 3

Figure 6.7 – Weld Axis HT12 3-phase wiring diagram (3 of 4)













## 6 : A P P E N D I X

---

### **RUNG 035 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press6      |
|----|/|----+----| |----+----| |----+----|/|----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 010      |
```

### **RUNG 036 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press7      |
|----| |----+----| |----+----| |----+----|/|----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 011      |
```

### **RUNG 037 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press8      |
|----|/|----+----|/|----+----|/|----+----| |----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 012      |
```

### **RUNG 038 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press9      |
|----| |----+----|/|----+----|/|----+----| |----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 013      |
```

### **RUNG 039 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press10     |
|----|/|----+----| |----+----|/|----+----| |----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 014     |
```

### **RUNG 040 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press11     |
|----| |----+----| |----+----|/|----+----| |----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 015     |
```

### **RUNG 041 User Rung Comment**

```
| Binary 1      Binary 2      Binary 4      Binary 8      ManualOR      Press12     |
|----|/|----+----|/|----+----| |----+----| |----+----| |----+----( )----|
| LF 001      LF 002      LF 003      LF 004      LF 011      PTS 016     |
```

**RUNG 042 User Rung Comment**

```
| Binary 1   Binary 2   Binary 4   Binary 8   ManualOR   Press13 |
|----| |-----+-----|/|-----+-----| |-----+-----| |-----+-----| |-----+----- ( )-----|
| LF 001     LF 002     LF 003     LF 004     LF 011     PTS 017 |
```

**RUNG 043 User Rung Comment**

```
| Binary 1   Binary 2   Binary 4   Binary 8   ManualOR   Press14 |
|----|/|-----+-----| |-----+-----| |-----+-----| |-----+-----| |-----+----- ( )-----|
| LF 001     LF 002     LF 003     LF 004     LF 011     PTS 018 |
```

**RUNG 044 User Rung Comment**

```
| Binary 1   Binary 2   Binary 4   Binary 8   ManualOR   Press15 |
|----| |-----+-----| |-----+-----| |-----+-----| |-----+-----| |-----+----- ( )-----|
| LF 001     LF 002     LF 003     LF 004     LF 011     PTS 019 |
```

**RUNG 045 User Rung Comment**

```
| Close      Opened0      Backup 1   Backup 2   Backup 4   Open 0   |
|----|/|-----+-----|/|-----+-----|/|-----+-----|/|-----+-----|/|-----+----- ( )-----|
| LF 005     STP 003     LF 006     LF 007     LF 008     PTS 021 |
```

**RUNG 046 User Rung Comment**

```
| Close      Opened1      Backup 1   Backup 2   Backup 4   Open 1   |
|----|/|-----+-----|/|-----+-----| |-----+-----|/|-----+-----|/|-----+----- ( )-----|
| LF 005     STP 004     LF 006     LF 007     LF 008     PTS 022 |
```

**RUNG 047 User Rung Comment**

```
| Close      opened2      Backup 1   Backup 2   Backup 4   Open 2   |
|----|/|-----+-----|/|-----+-----|/|-----+-----| |-----+-----|/|-----+----- ( )-----|
| LF 005     STP 005     LF 006     LF 007     LF 008     PTS 023 |
```

**RUNG 048 User Rung Comment**

```
| Close      opened3      Backup 1   Backup 2   Backup 4   Open 3   |
|----|/|-----+-----|/|-----+-----| |-----+-----| |-----+-----|/|-----+----- ( )-----|
| LF 005     STP 006     LF 006     LF 007     LF 008     PTS 024 |
```

6 : A P P E N D I X

---

**RUNG 049 User Rung Comment**

```
| Close      opened4      Backup 1      Backup 2      Backup 4      Open 4      |
|----|/|----+----|/|----+----|/|----+----|/|----+----|/|----+----( )----|
| LF 005      STP 007      LF 006      LF 007      LF 008      PTS 025      |
```

**RUNG 050 User Rung Comment**

```
| Close      opened5      Backup 1      Backup 2      Backup 4      open 5      |
|----|/|----+----|/|----+----|/|----+----|/|----+----|/|----+----( )----|
| LF 005      STP 008      LF 006      LF 007      LF 008      PTS 026      |
```

**RUNG 051 User Rung Comment**

```
| Close      opened6      Backup 1      Backup 2      Backup 4      open 6      |
|----|/|----+----|/|----+----|/|----+----|/|----+----|/|----+----( )----|
| LF 005      STP 009      LF 006      LF 007      LF 008      PTS 027      |
```

**RUNG 052 User Rung Comment**

```
| Close      opened7      Backup 1      Backup 2      Backup 4      open 7      |
|----|/|----+----|/|----+----|/|----+----|/|----+----|/|----+----( )----|
| LF 005      STP 010      LF 006      LF 007      LF 008      PTS 028      |
```

**RUNG 053 User Rung Comment**

```
| DoCalib    Close      Manual      dontrun      DoCalibr      |
|----|/|----+----|/|----+----|/|----+----|/|----+----+----+----( )----|
| FF 001      LF 005      FF 002      LF 016      PTS 030      |
```

**RUNG 054 User Rung Comment**

```
| Manual      Close      CloseSet      SetClose      |
|----|/|----+----|/|----+----|/|----+----+----+----( )----|
| FF 002      LF 005      FF 003      PTS 031      |
|           |           |           |           | |
| New Cap    Close      |           |
|----|/|----+----|/|----+----+----+----|
| LF 017      LF 005      |           |
```





## 6.6 Axiom Plus Standard Sequential Program

### **Line#001**

label:  
 comment: user comment for line #0001  
 Assign Register - VEL 001 = 3.00

### **Line#002**

label:  
 comment: user comment for line #0002  
 Position Compare - Branch Label: DONE  
 Comparison: Command Position < PNV 027 CWLimit

### **Line#003**

label:  
 comment: user comment for line #0003  
 Conditional Branch to Label: DONE  
 Conditional Operand: PLC-to-SEQ PRG FLAG #036 : PTS 036  
 Branch on Logic 1 (normally-open)

### **Line#004**

label:  
 comment: user comment for line #0004  
 Assign Register - PNV 027 CWLimit = 999.990

### **Line#005**

label: DONE  
 comment: user comment for line #0005  
 Time Delay: 1 seconds

### **Line#006**

label:  
 comment: Set the In-Position Band  
 Set In-Position Band = 1500 Encoder Counts,  
 or 0.075 inch

### **Line#007**

label:  
 comment: user comment for line #0007  
 Set/Clear Flag Bit -- CLEAR STP 003  
 CLEAR SEQ PRG-to-PLC FLAG #003 : STP 003

### **Line#008**

label:  
 comment: user comment for line #0008  
 Set/Clear Flag Bit -- CLEAR STP 004  
 CLEAR SEQ PRG-to-PLC FLAG #004 : STP 004

### **Line#009**

label: LOOP1  
 comment: user comment for line #0009  
 Conditional Subroutine Call: HOME  
 Conditional Operand: PLC-to-SEQ PRG FLAG #002 : PTS 002  
 Call Subroutine on Logic 1 (normally-open)

### **Line#010**

label:  
 comment: Flag ext computer, move done  
 Set/Clear Flag Bit -- CLEAR STP 015  
 CLEAR SEQ PRG-to-PLC FLAG #015 : STP 015

### **Line#011**

label:  
 comment: user comment for line #0011  
 Set/Clear Flag Bit -- CLEAR STP 020  
 CLEAR SEQ PRG-to-PLC FLAG #020 : STP 020

### **Line#012**

label:  
 comment: user comment for line #0012  
 Conditional Subroutine Call: CLOSEPOS  
 Conditional Operand: PLC-to-SEQ PRG FLAG #031 : PTS 031  
 Call Subroutine on Logic 1 (normally-open)

### **Line#013**

label:  
 comment: user comment for line #0013  
 Conditional Subroutine Call: CLOSELIM  
 Conditional Operand: PLC-to-SEQ PRG FLAG #032 : PTS 032  
 Call Subroutine on Logic 1 (normally-open)

**Line#014**

label:  
comment: user comment for line #0014  
Conditional Subroutine Call: CALIB  
Conditional Operand: PLC-to-SEQ PRG FLAG #030 : PTS 030  
Call Subroutine on Logic 1 (normally-open)

**Line#015**

label:  
comment: user comment for line #0015  
Conditional Subroutine Call: CAPCHECK  
Conditional Operand: PLC-to-SEQ PRG FLAG #029 : PTS 029  
Call Subroutine on Logic 1 (normally-open)

**Line#016**

label:  
comment: user comment for line #0016  
Conditional Subroutine Call: PRESS1  
Conditional Operand: PLC-to-SEQ PRG FLAG #005 : PTS 005  
Call Subroutine on Logic 1 (normally-open)

**Line#017**

label:  
comment: user comment for line #0017  
Conditional Subroutine Call: PRESS2  
Conditional Operand: PLC-to-SEQ PRG FLAG #006 : PTS 006  
Call Subroutine on Logic 1 (normally-open)

**Line#018**

label:  
comment: user comment for line #0018  
Conditional Subroutine Call: PRESS3  
Conditional Operand: PLC-to-SEQ PRG FLAG #007 : PTS 007  
Call Subroutine on Logic 1 (normally-open)

**Line#019**

label:  
comment: user comment for line #0019  
Conditional Subroutine Call: PRESS4  
Conditional Operand: PLC-to-SEQ PRG FLAG #008 : PTS 008  
Call Subroutine on Logic 1 (normally-open)

**Line#020**

label:  
comment: user comment for line #0020  
Conditional Subroutine Call: PRESS5  
Conditional Operand: PLC-to-SEQ PRG FLAG #009 : PTS 009  
Call Subroutine on Logic 1 (normally-open)

**Line#021**

label:  
comment: user comment for line #0021  
Conditional Subroutine Call: PRESS6  
Conditional Operand: PLC-to-SEQ PRG FLAG #010 : PTS 010  
Call Subroutine on Logic 1 (normally-open)

**Line#022**

label:  
comment: user comment for line #0022  
Conditional Subroutine Call: PRESS7  
Conditional Operand: PLC-to-SEQ PRG FLAG #011 : PTS 011  
Call Subroutine on Logic 1 (normally-open)

**Line#023**

label:  
comment: user comment for line #0023  
Conditional Subroutine Call: PRESS8  
Conditional Operand: PLC-to-SEQ PRG FLAG #012 : PTS 012  
Call Subroutine on Logic 1 (normally-open)

**Line#024**

label:  
comment: user comment for line #0024  
Conditional Subroutine Call: PRESS9  
Conditional Operand: PLC-to-SEQ PRG FLAG #013 : PTS 013  
Call Subroutine on Logic 1 (normally-open)

**Line#025**

label:  
comment: user comment for line #0025  
Conditional Subroutine Call: PRESS10  
Conditional Operand: PLC-to-SEQ PRG FLAG #014 : PTS 014  
Call Subroutine on Logic 1 (normally-open)

**Line#026**

label:  
 comment: user comment for line #0026  
 Conditional Subroutine Call: PRESS11  
 Conditional Operand: PLC-to-SEQ PRG FLAG #015 : PTS 015  
 Call Subroutine on Logic 1 (normally-open)

**Line#027**

label:  
 comment: user comment for line #0027  
 Conditional Subroutine Call: PRESS12  
 Conditional Operand: PLC-to-SEQ PRG FLAG #016 : PTS 016  
 Call Subroutine on Logic 1 (normally-open)

**Line#028**

label:  
 comment: user comment for line #0028  
 Conditional Subroutine Call: PRESS13  
 Conditional Operand: PLC-to-SEQ PRG FLAG #017 : PTS 017  
 Call Subroutine on Logic 1 (normally-open)

**Line#029**

label:  
 comment: user comment for line #0029  
 Conditional Subroutine Call: PRESS14  
 Conditional Operand: PLC-to-SEQ PRG FLAG #018 : PTS 018  
 Call Subroutine on Logic 1 (normally-open)

**Line#030**

label:  
 comment: user comment for line #0030  
 Conditional Subroutine Call: PRESS15  
 Conditional Operand: PLC-to-SEQ PRG FLAG #019 : PTS 019  
 Call Subroutine on Logic 1 (normally-open)

**Line#031**

label:  
 comment: user comment for line #0031  
 Conditional Subroutine Call: OPEN0  
 Conditional Operand: PLC-to-SEQ PRG FLAG #021 : PTS 021  
 Call Subroutine on Logic 1 (normally-open)

**Line#032**

label:  
 comment: user comment for line #0032  
 Conditional Subroutine Call: OPEN1  
 Conditional Operand: PLC-to-SEQ PRG FLAG #022 : PTS 022  
 Call Subroutine on Logic 1 (normally-open)

**Line#033**

label:  
 comment: user comment for line #0033  
 Conditional Subroutine Call: OPEN2  
 Conditional Operand: PLC-to-SEQ PRG FLAG #023 : PTS 023  
 Call Subroutine on Logic 1 (normally-open)

**Line#034**

label:  
 comment: user comment for line #0034  
 Conditional Subroutine Call: OPEN3  
 Conditional Operand: PLC-to-SEQ PRG FLAG #024 : PTS 024  
 Call Subroutine on Logic 1 (normally-open)

**Line#035**

label:  
 comment: user comment for line #0035  
 Conditional Subroutine Call: OPEN4  
 Conditional Operand: PLC-to-SEQ PRG FLAG #025 : PTS 025  
 Call Subroutine on Logic 1 (normally-open)

**Line#036**

label:  
 comment: user comment for line #0036  
 Conditional Subroutine Call: OPEN5  
 Conditional Operand: PLC-to-SEQ PRG FLAG #026 : PTS 026  
 Call Subroutine on Logic 1 (normally-open)

**Line#037**

label:  
 comment: user comment for line #0037  
 Conditional Subroutine Call: OPEN6  
 Conditional Operand: PLC-to-SEQ PRG FLAG #027 : PTS 027  
 Call Subroutine on Logic 1 (normally-open)

**Line#038**

label:  
comment: user comment for line #0038  
Conditional Subroutine Call: OPEN7  
Conditional Operand: PLC-to-SEQ PRG FLAG #028 : PTS 028  
Call Subroutine on Logic 1 (normally-open)

**Line#039**

label:  
comment: user comment for line #0039  
Branch to Label: LOOP1

**Line#040**

label: OPENO  
comment: user comment for line #0040  
Call Subroutine with Start Label: OPENSTRT

**Line#041**

label:  
comment: Move to open position  
Abs Position Move -- Position = PNV 001-  
Vel = 1.00 Acc = 799.999 Dec = 799.999  
Trigger #1: PLC-to-PRG Flag #003 Logic One  
Action #1 (Trig #1): New Speed = VEL 001  
Action #2 (Trig #1): New Torque Limit = 100.0%  
Trigger #2: No Trigger Event

**Line#042**

label:  
comment: user comment for line #0042  
Set/Clear Flag Bit -- CLEAR STP 011  
CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#043**

label:  
comment: user comment for line #0043  
Set/Clear Flag Bit -- SET STP 003  
SET SEQ PRG-to-PLC FLAG #003 : STP 003

**Line#044**

label:  
comment: user comment for line #0044  
Set/Clear Flag Bit -- SET STP 018  
SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#045**

label:  
comment: user comment for line #0045  
Return from Subroutine

**Line#046**

label: OPEN1  
comment: user comment for line #0046  
Call Subroutine with Start Label: OPENSTRT

**Line#047**

label:  
comment: Move to open position  
Abs Position Move -- Position = PNV 002-  
Vel = 1.00 Acc = 500.0 Dec = 500.0  
Trigger #1: PLC-to-PRG Flag #003 Logic One  
Action #1 (Trig #1): New Speed = VEL 001  
Action #2 (Trig #1): New Torque Limit = 100.0%  
Trigger #2: No Trigger Event

**Line#048**

label:  
comment: user comment for line #0048  
Set/Clear Flag Bit -- CLEAR STP 011  
CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#049**

label:  
comment: user comment for line #0049  
Set/Clear Flag Bit -- SET STP 004  
SET SEQ PRG-to-PLC FLAG #004 : STP 004

**Line#050**

label:  
 comment: user comment for line #0050  
 Set/Clear Flag Bit -- SET STP 018  
 SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#051**

label:  
 comment: user comment for line #0051  
 Return from Subroutine

**Line#052**

label: OPEN2  
 comment: user comment for line #0052  
 Call Subroutine with Start Label: OPENSTRT

**Line#053**

label:  
 comment: Move to open position  
 Abs Position Move -- Position = PNV 003-  
 Vel = 1.00 Acc = 500.0 Dec = 500.0  
 Trigger #1: PLC-to-PRG Flag #003 Logic One  
 Action #1 (Trig #1): New Speed = VEL 001  
 Action #2 (Trig #1): New Torque Limit = 100.0%  
 Trigger #2: No Trigger Event

**Line#054**

label:  
 comment: user comment for line #0054  
 Set/Clear Flag Bit -- CLEAR STP 011  
 CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#055**

label:  
 comment: user comment for line #0055  
 Set/Clear Flag Bit -- SET STP 005  
 SET SEQ PRG-to-PLC FLAG #005 : STP 005

**Line#056**

label:  
 comment: user comment for line #0056  
 Set/Clear Flag Bit -- SET STP 018  
 SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#057**

label:  
 comment: user comment for line #0057  
 Return from Subroutine

**Line#058**

label: OPEN3  
 comment: user comment for line #0058  
 Call Subroutine with Start Label: OPENSTRT

**Line#059**

label:  
 comment: Move to open position  
 Abs Position Move -- Position = PNV 004-  
 Vel = 1.00 Acc = 500.0 Dec = 500.0  
 Trigger #1: PLC-to-PRG Flag #003 Logic One  
 Action #1 (Trig #1): New Speed = VEL 001  
 Action #2 (Trig #1): New Torque Limit = 100.0%  
 Trigger #2: No Trigger Event

**Line#060**

label:  
 comment: user comment for line #0060  
 Set/Clear Flag Bit -- CLEAR STP 011  
 CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#061**

label:  
 comment: user comment for line #0061  
 Set/Clear Flag Bit -- SET STP 006  
 SET SEQ PRG-to-PLC FLAG #006 : STP 006

**Line#062**

label:  
 comment: user comment for line #0062  
 Set/Clear Flag Bit -- SET STP 018  
 SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#063**

label:  
 comment: user comment for line #0063  
 Return from Subroutine

---

**Line#064**

label: OPEN4  
comment: user comment for line #0064  
Call Subroutine with Start Label: OPENSTRT

**Line#065**

label:  
comment: Move to open position  
Abs Position Move -- Position = PNV 005-  
Vel = 1.00 Acc = 500.0 Dec = 500.0  
Trigger #1: PLC-to-PRG Flag #003 Logic One  
Action #1 (Trig #1): New Speed = VEL 001  
Action #2 (Trig #1): New Torque Limit = 100.0%  
Trigger #2: No Trigger Event

**Line#066**

label:  
comment: user comment for line #0066  
Set/Clear Flag Bit -- CLEAR STP 011  
CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#067**

label:  
comment: user comment for line #0067  
Set/Clear Flag Bit -- SET STP 007  
SET SEQ PRG-to-PLC FLAG #007 : STP 007

**Line#068**

label:  
comment: user comment for line #0068  
Set/Clear Flag Bit -- SET STP 018  
SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#069**

label:  
comment: user comment for line #0069  
Return from Subroutine

**Line#070**

label: OPEN5  
comment: user comment for line #0070  
Call Subroutine with Start Label: OPENSTRT

**Line#071**

label:  
comment: Move to open position  
Abs Position Move -- Position = PNV 006-  
Vel = 1.00 Acc = 500.0 Dec = 500.0  
Trigger #1: PLC-to-PRG Flag #003 Logic One  
Action #1 (Trig #1): New Speed = VEL 001  
Action #2 (Trig #1): New Torque Limit = 100.0%  
Trigger #2: No Trigger Event

**Line#072**

label:  
comment: user comment for line #0072  
Set/Clear Flag Bit -- CLEAR STP 011  
CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#073**

label:  
comment: user comment for line #0073  
Set/Clear Flag Bit -- SET STP 008  
SET SEQ PRG-to-PLC FLAG #008 : STP 008

**Line#074**

label:  
comment: user comment for line #0074  
Set/Clear Flag Bit -- SET STP 018  
SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#075**

label:  
comment: user comment for line #0075  
Return from Subroutine

**Line#076**

label: OPEN6  
comment: user comment for line #0076  
Call Subroutine with Start Label: OPENSTRT

**Line#077**

label:  
 comment: Move to open position  
 Abs Position Move -- Position = PNV 007-  
 Vel = 1.00 Acc = 500.0 Dec = 500.0  
 Trigger #1: PLC-to-PRG Flag #003 Logic One  
 Action #1 (Trig #1): New Speed = VEL 001  
 Action #2 (Trig #1): New Torque Limit = 100.0%  
 Trigger #2: No Trigger Event

**Line#078**

label:  
 comment: user comment for line #0078  
 Set/Clear Flag Bit -- CLEAR STP 011  
 CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#079**

label:  
 comment: user comment for line #0079  
 Set/Clear Flag Bit -- SET STP 009  
 SET SEQ PRG-to-PLC FLAG #009 : STP 009

**Line#080**

label:  
 comment: user comment for line #0080  
 Set/Clear Flag Bit -- SET STP 018  
 SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#081**

label:  
 comment: user comment for line #0081  
 Return from Subroutine

**Line#082**

label: OPEN7  
 comment: user comment for line #0082  
 Call Subroutine with Start Label: OPENSTRT

**Line#083**

label:  
 comment: Move to open position  
 Abs Position Move -- Position = PNV 008-  
 Vel = 1.00 Acc = 500.0 Dec = 500.0  
 Trigger #1: PLC-to-PRG Flag #003 Logic One  
 Action #1 (Trig #1): New Speed = VEL 001  
 Action #2 (Trig #1): New Torque Limit = 100.0%  
 Trigger #2: No Trigger Event

**Line#084**

label:  
 comment: user comment for line #0084  
 Set/Clear Flag Bit -- CLEAR STP 011  
 CLEAR SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#085**

label:  
 comment: user comment for line #0085  
 Set/Clear Flag Bit -- SET STP 010  
 SET SEQ PRG-to-PLC FLAG #010 : STP 010

**Line#086**

label:  
 comment: user comment for line #0086  
 Set/Clear Flag Bit -- SET STP 018  
 SET SEQ PRG-to-PLC FLAG #018 : STP 018

**Line#087**

label:  
 comment: user comment for line #0087  
 Return from Subroutine

**Line#088**

label: HOME  
 comment: Low torque for home  
 Set Maximum Torque Limit -- 30.0 %

**Line#089**

label:  
comment: user comment for line #0089  
Set/Clear Flag Bit -- SET STP 002  
SET SEQ PRG-to-PLC FLAG #002 : STP 002

**Line#090**

label:  
comment: user comment for line #0090  
Velocity Move -- Velocity = -0.50 inch / sec  
Acc = 20.0 Dec = 100.0  
Trigger #1: PLC-to-PRG Flag #001 Logic One  
Action #1 (Trig #1): Terminate Motion Instruction  
Action #2 (Trig #1): No Action  
Trigger #2: No Trigger Event

**Line#091**

label:  
comment: user comment for line #0091  
Set/Clear Flag Bit -- CLEAR STP 002  
CLEAR SEQ PRG-to-PLC FLAG #002 : STP 002

**Line#092**

label:  
comment: user comment for line #0092  
Set Command Position = Actual -- Zero Following Error

**Line#093**

label:  
comment: user comment for line #0093  
Inc Position Move -- Distance = 0.125 inch  
Vel = 1.00 Acc = 4.998 Dec = 4.998  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#094**

label:  
comment: define pos as "Home"  
Define Present Absolute Position  
Define Absolute COMMAND Position as 0.000 inch

**Line#095**

label:  
comment: user comment for line #0095  
Return from Subroutine

**Line#096**

label: PRESS1  
comment: user comment for line #0096  
Call Subroutine with Start Label: CLOSESET

**Line#097**

label:  
comment: user comment for line #0097  
Abs Position Move -- Position = PNV 010-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#098**

label:  
comment: user comment for line #0098  
Wait for Input / Flag -- IN 014 -- Logic 1  
Conditional Operand: PHYSICAL INPUT #014 : IN 014  
Continue on Logic 1 (normally-open)  
Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#099**

label:  
comment: user comment for line #0099  
Set Maximum Torque Limit -- TNV 001 %

**Line#100**

label:  
comment: user comment for line #0100  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#101**

label:  
 comment: user comment for line #0101  
 Conditional Branch to Label: PR1GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#102**

label:  
 comment: user comment for line #0102  
 Position Compare - Branch Label: PR1STOP  
 Comparison: Actual Position < PNV 010

**Line#103**

label:  
 comment: user comment for line #0103  
 Position Compare - Branch Label: PR1GO  
 Comparison: Actual Position < POS 001

**Line#104**

label: PR1STOP  
 comment: user comment for line #0104  
 Call Subroutine with Start Label: NOTPOS

**Line#105**

label: PR1GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#106**

label:  
 comment: user comment for line #0106  
 Conditional Branch to Label: EXIT1  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#107**

label:  
 comment: user comment for line #0107  
 Store Position to Register: POS 016-  
 Store Absolute ACTUAL Position

**Line#108**

label: EXIT1  
 comment: user comment for line #0108  
 Return from Subroutine

**Line#109**

label: PRESS2  
 comment: user comment for line #0109  
 Call Subroutine with Start Label: CLOSESET

**Line#110**

label:  
 comment: user comment for line #0110  
 Abs Position Move -- Position = PNV 011-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#111**

label:  
 comment: user comment for line #0111  
 Set Maximum Torque Limit -- TNV 002 %

**Line#112**

label:  
 comment: user comment for line #0112  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#113**

label:  
 comment: user comment for line #0113  
 Conditional Branch to Label: PR2GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#114**

label:  
comment: user comment for line #0114  
Position Compare - Branch Label: PR2STOP  
Comparison: Actual Position < PNV 011

**Line#115**

label:  
comment: user comment for line #0115  
Position Compare - Branch Label: PR2GO  
Comparison: Actual Position < POS 002

**Line#116**

label: PR2STOP  
comment: user comment for line #0116  
Call Subroutine with Start Label: NOTPOS

**Line#117**

label: PR2GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#118**

label:  
comment: user comment for line #0118  
Conditional Branch to Label: EXIT2  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#119**

label:  
comment: user comment for line #0119  
Store Position to Register: POS 017-  
Store Absolute ACTUAL Position

**Line#120**

label: EXIT2  
comment: user comment for line #0120  
Return from Subroutine

**Line#121**

label: PRESS3  
comment: user comment for line #0121  
Call Subroutine with Start Label: CLOSESET

**Line#122**

label:  
comment: user comment for line #0122  
Abs Position Move -- Position = PNV 012-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#123**

label:  
comment: user comment for line #0123  
Set Maximum Torque Limit -- TNV 003 %

**Line#124**

label:  
comment: user comment for line #0124  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#125**

label:  
comment: user comment for line #0125  
Conditional Branch to Label: PR3GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#126**

label:  
comment: user comment for line #0126  
Position Compare - Branch Label: PR3STOP  
Comparison: Actual Position < PNV 012

**Line#127**

label:  
 comment: user comment for line #0127  
 Position Compare - Branch Label: PR3GO  
 Comparison: Actual Position < POS 003

**Line#128**

label: PR3STOP  
 comment: user comment for line #0128  
 Call Subroutine with Start Label: NOTPOS

**Line#129**

label: PR3GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#130**

label:  
 comment: user comment for line #0130  
 Conditional Branch to Label: EXIT3  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#131**

label:  
 comment: user comment for line #0131  
 Store Position to Register: POS 018-  
 Store Absolute ACTUAL Position

**Line#132**

label: EXIT3  
 comment: user comment for line #0132  
 Return from Subroutine

**Line#133**

label: PRESS4  
 comment: user comment for line #0133  
 Call Subroutine with Start Label: CLOSESET

**Line#134**

label:  
 comment: user comment for line #0134  
 Abs Position Move -- Position = PNV 013-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#135**

label:  
 comment: user comment for line #0135  
 Set Maximum Torque Limit -- TNV 004 %

**Line#136**

label:  
 comment: user comment for line #0136  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#137**

label:  
 comment: user comment for line #0137  
 Conditional Branch to Label: PR4GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#138**

label:  
 comment: user comment for line #0138  
 Position Compare - Branch Label: PR4STOP  
 Comparison: Actual Position < PNV 013

**Line#139**

label:  
 comment: user comment for line #0139  
 Position Compare - Branch Label: PR4GO  
 Comparison: Actual Position < POS 004

**Line#140**

label: PR4STOP  
comment: user comment for line #0140  
Call Subroutine with Start Label: NOTPOS

**Line#141**

label: PR4GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#142**

label:  
comment: user comment for line #0142  
Conditional Branch to Label: EXIT4  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#143**

label:  
comment: user comment for line #0143  
Store Position to Register: POS 019-  
Store Absolute ACTUAL Position

**Line#144**

label: EXIT4  
comment: user comment for line #0144  
Return from Subroutine

**Line#145**

label: PRESS5  
comment: user comment for line #0145  
Call Subroutine with Start Label: CLOSESET

**Line#146**

label:  
comment: user comment for line #0146  
Abs Position Move -- Position = PNV 014-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#147**

label:  
comment: user comment for line #0147  
Set Maximum Torque Limit -- TNV 005 %

**Line#148**

label:  
comment: user comment for line #0148  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#149**

label:  
comment: user comment for line #0149  
Conditional Branch to Label: PR5GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#150**

label:  
comment: user comment for line #0150  
Position Compare - Branch Label: PR5STOP  
Comparison: Actual Position < PNV 014

**Line#151**

label:  
comment: user comment for line #0151  
Position Compare - Branch Label: PR5GO  
Comparison: Actual Position < POS 005

**Line#152**

label: PR5STOP  
comment: user comment for line #0152  
Call Subroutine with Start Label: NOTPOS

**Line#153**

label: PR5GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#154**

label:  
 comment: user comment for line #0154  
 Conditional Branch to Label: EXIT5  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#155**

label:  
 comment: user comment for line #0155  
 Store Position to Register: POS 020-  
 Store Absolute ACTUAL Position

**Line#156**

label: EXIT5  
 comment: user comment for line #0156  
 Return from Subroutine

**Line#157**

label: PRESS6  
 comment: user comment for line #0157  
 Call Subroutine with Start Label: CLOSESET

**Line#158**

label:  
 comment: user comment for line #0158  
 Abs Position Move -- Position = PNV 015-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#159**

label:  
 comment: user comment for line #0159  
 Set Maximum Torque Limit -- TNV 006 %

**Line#160**

label:  
 comment: user comment for line #0160  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#161**

label:  
 comment: user comment for line #0161  
 Conditional Branch to Label: PR6GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#162**

label:  
 comment: user comment for line #0162  
 Position Compare - Branch Label: PR6STOP  
 Comparison: Actual Position < PNV 015

**Line#163**

label:  
 comment: user comment for line #0163  
 Position Compare - Branch Label: PR6GO  
 Comparison: Actual Position < POS 006

**Line#164**

label: PR6STOP  
 comment: user comment for line #0164  
 Call Subroutine with Start Label: NOTPOS

**Line#165**

label: PR6GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#166**

label:  
comment: user comment for line #0166  
Conditional Branch to Label: EXIT6  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#167**

label:  
comment: user comment for line #0167  
Store Position to Register: POS 021-  
Store Absolute ACTUAL Position

**Line#168**

label: EXIT6  
comment: user comment for line #0168  
Return from Subroutine

**Line#169**

label: PRESS7  
comment: user comment for line #0169  
Call Subroutine with Start Label: CLOSESET

**Line#170**

label:  
comment: user comment for line #0170  
Abs Position Move -- Position = PNV 016-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#171**

label:  
comment: user comment for line #0171  
Set Maximum Torque Limit -- TNV 007 %

**Line#172**

label:  
comment: user comment for line #0172  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#173**

label:  
comment: user comment for line #0173  
Conditional Branch to Label: PR7GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#174**

label:  
comment: user comment for line #0174  
Position Compare - Branch Label: PR7STOP  
Comparison: Actual Position < PNV 016

**Line#175**

label:  
comment: user comment for line #0175  
Position Compare - Branch Label: PR7GO  
Comparison: Actual Position < POS 007

**Line#176**

label: PR7STOP  
comment: user comment for line #0176  
Call Subroutine with Start Label: NOTPOS

**Line#177**

label: PR7GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#178**

label:  
 comment: user comment for line #0178  
 Conditional Branch to Label: EXIT7  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#179**

label:  
 comment: user comment for line #0179  
 Store Position to Register: POS 022-  
 Store Absolute ACTUAL Position

**Line#180**

label: EXIT7  
 comment: user comment for line #0180  
 Return from Subroutine

**Line#181**

label: PRESS8  
 comment: user comment for line #0181  
 Call Subroutine with Start Label: CLOSESET

**Line#182**

label:  
 comment: user comment for line #0182  
 Abs Position Move -- Position = PNV 017-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#183**

label:  
 comment: user comment for line #0183  
 Set Maximum Torque Limit -- TNV 008 %

**Line#184**

label:  
 comment: user comment for line #0184  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#185**

label:  
 comment: user comment for line #0185  
 Conditional Branch to Label: PR8GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#186**

label:  
 comment: user comment for line #0186  
 Position Compare - Branch Label: PR8STOP  
 Comparison: Actual Position < PNV 017

**Line#187**

label:  
 comment: user comment for line #0187  
 Position Compare - Branch Label: PR8GO  
 Comparison: Actual Position < POS 008

**Line#188**

label: PR8STOP  
 comment: user comment for line #0188  
 Call Subroutine with Start Label: NOTPOS

**Line#189**

label: PR8GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#190**

label:  
comment: user comment for line #0190  
Conditional Branch to Label: EXIT8  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#191**

label:  
comment: user comment for line #0191  
Store Position to Register: POS 023-  
Store Absolute ACTUAL Position

**Line#192**

label: EXIT8  
comment: user comment for line #0192  
Return from Subroutine

**Line#193**

label: PRESS9  
comment: user comment for line #0193  
Call Subroutine with Start Label: CLOSESET

**Line#194**

label:  
comment: user comment for line #0194  
Abs Position Move -- Position = PNV 018-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#195**

label:  
comment: user comment for line #0195  
Set Maximum Torque Limit -- TNV 009 %

**Line#196**

label:  
comment: user comment for line #0196  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#197**

label:  
comment: user comment for line #0197  
Conditional Branch to Label: PR9GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#198**

label:  
comment: user comment for line #0198  
Position Compare - Branch Label: PR9STOP  
Comparison: Actual Position < PNV 018

**Line#199**

label:  
comment: user comment for line #0199  
Position Compare - Branch Label: PR9GO  
Comparison: Actual Position < POS 009

**Line#200**

label: PR9STOP  
comment: user comment for line #0200  
Call Subroutine with Start Label: NOTPOS

**Line#201**

label: PR9GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#202**

label:  
 comment: user comment for line #0202  
 Conditional Branch to Label: EXIT9  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#203**

label:  
 comment: user comment for line #0203  
 Store Position to Register: POS 024-  
 Store Absolute ACTUAL Position

**Line#204**

label: EXIT9  
 comment: user comment for line #0204  
 Return from Subroutine

**Line#205**

label: PRESS10  
 comment: user comment for line #0205  
 Call Subroutine with Start Label: CLOSESET

**Line#206**

label:  
 comment: user comment for line #0206  
 Abs Position Move -- Position = PNV 019-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#207**

label:  
 comment: user comment for line #0207  
 Set Maximum Torque Limit -- TNV 010 %

**Line#208**

label:  
 comment: user comment for line #0208  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#209**

label:  
 comment: user comment for line #0209  
 Conditional Branch to Label: PR10GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#210**

label:  
 comment: user comment for line #0210  
 Position Compare - Branch Label: PR10STOP  
 Comparison: Actual Position < PNV 019

**Line#211**

label:  
 comment: user comment for line #0211  
 Position Compare - Branch Label: PR10GO  
 Comparison: Actual Position < POS 010

**Line#212**

label: PR10STOP  
 comment: user comment for line #0212  
 Call Subroutine with Start Label: NOTPOS

**Line#213**

label: PR10GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#214**

label:  
comment: user comment for line #0214  
Conditional Branch to Label: EXIT10  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#215**

label:  
comment: user comment for line #0215  
Store Position to Register: POS 025-  
Store Absolute ACTUAL Position

**Line#216**

label: EXIT10  
comment: user comment for line #0216  
Return from Subroutine

**Line#217**

label: PRESS11  
comment: user comment for line #0217  
Call Subroutine with Start Label: CLOSESET

**Line#218**

label:  
comment: user comment for line #0218  
Abs Position Move -- Position = PNV 020-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#219**

label:  
comment: user comment for line #0219  
Set Maximum Torque Limit -- TNV 011 %

**Line#220**

label:  
comment: user comment for line #0220  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#221**

label:  
comment: user comment for line #0221  
Conditional Branch to Label: PR11GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#222**

label:  
comment: user comment for line #0222  
Position Compare - Branch Label: PR11STOP  
Comparison: Actual Position < PNV 020

**Line#223**

label:  
comment: user comment for line #0223  
Position Compare - Branch Label: PR11GO  
Comparison: Actual Position < POS 011

**Line#224**

label: PR11STOP  
comment: user comment for line #0224  
Call Subroutine with Start Label: NOTPOS

**Line#225**

label: PR11GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#226**

label:  
 comment: user comment for line #0226  
 Conditional Branch to Label: EXIT11  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#227**

label:  
 comment: user comment for line #0227  
 Store Position to Register: POS 026-  
 Store Absolute ACTUAL Position

**Line#228**

label: EXIT11  
 comment: user comment for line #0228  
 Return from Subroutine

**Line#229**

label: PRESS12  
 comment: user comment for line #0229  
 Call Subroutine with Start Label: CLOSESET

**Line#230**

label:  
 comment: user comment for line #0230  
 Abs Position Move -- Position = PNV 021-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#231**

label:  
 comment: user comment for line #0231  
 Set Maximum Torque Limit -- TNV 012 %

**Line#232**

label:  
 comment: user comment for line #0232  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#233**

label:  
 comment: user comment for line #0233  
 Conditional Branch to Label: PR12GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#234**

label:  
 comment: user comment for line #0234  
 Position Compare - Branch Label: PR12STOP  
 Comparison: Actual Position < PNV 021

**Line#235**

label:  
 comment: user comment for line #0235  
 Position Compare - Branch Label: PR12GO  
 Comparison: Actual Position < POS 012

**Line#236**

label: PR12STOP  
 comment: user comment for line #0236  
 Call Subroutine with Start Label: NOTPOS

**Line#237**

label: PR12GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#238**

label:  
comment: user comment for line #0238  
Conditional Branch to Label: EXIT12  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#239**

label:  
comment: user comment for line #0239  
Store Position to Register: POS 027-  
Store Absolute ACTUAL Position

**Line#240**

label: EXIT12  
comment: user comment for line #0240  
Return from Subroutine

**Line#241**

label: PRESS13  
comment: user comment for line #0241  
Call Subroutine with Start Label: CLOSESET

**Line#242**

label:  
comment: user comment for line #0242  
Abs Position Move -- Position = PNV 022-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#243**

label:  
comment: user comment for line #0243  
Set Maximum Torque Limit -- TNV 013 %

**Line#244**

label:  
comment: user comment for line #0244  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#245**

label:  
comment: user comment for line #0245  
Conditional Branch to Label: PR13GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#246**

label:  
comment: user comment for line #0246  
Position Compare - Branch Label: PR13STOP  
Comparison: Actual Position < PNV 022

**Line#247**

label:  
comment: user comment for line #0247  
Position Compare - Branch Label: PR13GO  
Comparison: Actual Position < POS 013

**Line#248**

label: PR13STOP  
comment: user comment for line #0248  
Call Subroutine with Start Label: NOTPOS

**Line#249**

label: PR13GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#250**

label:  
 comment: user comment for line #0250  
 Conditional Branch to Label: EXIT13  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#251**

label:  
 comment: user comment for line #0251  
 Store Position to Register: POS 028-  
 Store Absolute ACTUAL Position

**Line#252**

label: EXIT13  
 comment: user comment for line #0252  
 Return from Subroutine

**Line#253**

label: PRESS14  
 comment: user comment for line #0253  
 Call Subroutine with Start Label: CLOSESET

**Line#254**

label:  
 comment: user comment for line #0254  
 Abs Position Move -- Position = PNV 023-  
 Vel = VEL 001- Acc = 500.0 Dec = 500.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#255**

label:  
 comment: user comment for line #0255  
 Set Maximum Torque Limit -- TNV 014 %

**Line#256**

label:  
 comment: user comment for line #0256  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 0.250 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#257**

label:  
 comment: user comment for line #0257  
 Conditional Branch to Label: PR14GO  
 Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
 Branch on Logic 0 (normally-closed)

**Line#258**

label:  
 comment: user comment for line #0258  
 Position Compare - Branch Label: PR14STOP  
 Comparison: Actual Position < PNV 023

**Line#259**

label:  
 comment: user comment for line #0259  
 Position Compare - Branch Label: PR14GO  
 Comparison: Actual Position < POS 014

**Line#260**

label: PR14STOP  
 comment: user comment for line #0260  
 Call Subroutine with Start Label: NOTPOS

**Line#261**

label: PR14GO  
 comment: Move to weld position  
 Call Subroutine with Start Label: CLOSEDN

**Line#262**

label:  
comment: user comment for line #0262  
Conditional Branch to Label: EXIT14  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#263**

label:  
comment: user comment for line #0263  
Store Position to Register: POS 029-  
Store Absolute ACTUAL Position

**Line#264**

label: EXIT14  
comment: user comment for line #0264  
Return from Subroutine

**Line#265**

label: PRESS15  
comment: user comment for line #0265  
Call Subroutine with Start Label: CLOSESET

**Line#266**

label:  
comment: user comment for line #0266  
Abs Position Move -- Position = PNV 024-  
Vel = VEL 001- Acc = 500.0 Dec = 500.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#267**

label:  
comment: user comment for line #0267  
Set Maximum Torque Limit -- TNV 015 %

**Line#268**

label:  
comment: user comment for line #0268  
Velocity Move -- Velocity = 1.00 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: Incremental Distance = 0.250 inch  
Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
Action #2 (Trig #1): No Action  
Trigger #2: PLC-to-PRG Flag #001, Logic One  
Action #1 (Trig #2): Terminate Motion Instruction  
Action #2 (Trig #2): No Action

**Line#269**

label:  
comment: user comment for line #0269  
Conditional Branch to Label: PR15GO  
Conditional Operand: PLC-to-SEQ PRG FLAG #033 : PTS 033  
Branch on Logic 0 (normally-closed)

**Line#270**

label:  
comment: user comment for line #0270  
Position Compare - Branch Label: PR15STOP  
Comparison: Actual Position < PNV 024

**Line#271**

label:  
comment: user comment for line #0271  
Position Compare - Branch Label: PR15GO  
Comparison: Actual Position < POS 015

**Line#272**

label: PR15STOP  
comment: user comment for line #0272  
Call Subroutine with Start Label: NOTPOS

**Line#273**

label: PR15GO  
comment: Move to weld position  
Call Subroutine with Start Label: CLOSEDN

**Line#274**

label:  
 comment: user comment for line #0274  
 Conditional Branch to Label: EXIT15  
 Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
 Branch on Logic 1 (normally-open)

**Line#275**

label:  
 comment: user comment for line #0275  
 Store Position to Register: POS 030-  
 Store Absolute ACTUAL Position

**Line#276**

label: EXIT15  
 comment: user comment for line #0276  
 Return from Subroutine

**Line#277**

label: CLEAR  
 comment: user comment for line #0277  
 Set/Clear Flag Bit -- CLEAR STP 003  
 CLEAR SEQ PRG-to-PLC FLAG #003 : STP 003

**Line#278**

label:  
 comment: user comment for line #0278  
 Set/Clear Flag Bit -- CLEAR STP 004  
 CLEAR SEQ PRG-to-PLC FLAG #004 : STP 004

**Line#279**

label:  
 comment: user comment for line #0279  
 Set/Clear Flag Bit -- CLEAR STP 001  
 CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#280**

label:  
 comment: user comment for line #0280  
 Set/Clear Flag Bit -- CLEAR STP 005  
 CLEAR SEQ PRG-to-PLC FLAG #005 : STP 005

**Line#281**

label:  
 comment: user comment for line #0281  
 Set/Clear Flag Bit -- CLEAR STP 006  
 CLEAR SEQ PRG-to-PLC FLAG #006 : STP 006

**Line#282**

label:  
 comment: user comment for line #0282  
 Set/Clear Flag Bit -- CLEAR STP 007  
 CLEAR SEQ PRG-to-PLC FLAG #007 : STP 007

**Line#283**

label:  
 comment: user comment for line #0283  
 Set/Clear Flag Bit -- CLEAR STP 008  
 CLEAR SEQ PRG-to-PLC FLAG #008 : STP 008

**Line#284**

label:  
 comment: user comment for line #0284  
 Set/Clear Flag Bit -- CLEAR STP 009  
 CLEAR SEQ PRG-to-PLC FLAG #009 : STP 009

**Line#285**

label:  
 comment: user comment for line #0285  
 Set/Clear Flag Bit -- CLEAR STP 010  
 CLEAR SEQ PRG-to-PLC FLAG #010 : STP 010

**Line#286**

label:  
 comment: user comment for line #0286  
 Set/Clear Flag Bit -- CLEAR STP 020  
 CLEAR SEQ PRG-to-PLC FLAG #020 : STP 020

**Line#287**

label:  
 comment: user comment for line #0287  
 Set/Clear Flag Bit -- CLEAR STP 018  
 CLEAR SEQ PRG-to-PLC FLAG #018 : STP 018

---

**Line#288**

label:  
comment: user comment for line #0288  
Return from Subroutine

**Line#289**

label: CLOSESET  
comment: user comment for line #0289  
Set Maximum Torque Limit -- 100.0 %

**Line#290**

label:  
comment: user comment for line #0290  
Call Subroutine with Start Label: CLEAR

**Line#291**

label:  
comment: user comment for line #0291  
Return from Subroutine

**Line#292**

label: CLOSEDN  
comment: user comment for line #0292  
Conditional Subroutine Call: NOTPOS  
Conditional Operand: PLC-to-SEQ PRG FLAG #004 : PTS 004  
Call Subroutine on Logic 0 (normally-closed)

**Line#293**

label:  
comment: user comment for line #0293  
Conditional Branch to Label: SKIP  
Conditional Operand: SEQ PRG-to-PLC FLAG #020 : STP 020  
Branch on Logic 1 (normally-open)

**Line#294**

label:  
comment: user comment for line #0294  
Set/Clear Flag Bit -- SET STP 021  
SET SEQ PRG-to-PLC FLAG #021 : STP 021

**Line#295**

label: SKIP  
comment: user comment for line #0295  
Set/Clear Flag Bit -- CLEAR STP 001  
CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#296**

label:  
comment: user comment for line #0296  
Wait for Input / Flag -- PTS 020 -- Logic 0  
Conditional Operand: PLC-to-SEQ PRG FLAG #020 : PTS 020  
Continue on Logic 0 (normally-closed)  
Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#297**

label:  
comment: user comment for line #0297  
Set Command Position = Actual -- Zero Following Error

**Line#298**

label: NOTORQUE  
comment: user comment for line #0298  
Return from Subroutine

**Line#299**

label: OPENSTRT  
comment: Open Position Binary 0  
Set/Clear Flag Bit -- CLEAR STP 021  
CLEAR SEQ PRG-to-PLC FLAG #021 : STP 021

**Line#300**

label:  
comment: user comment for line #0300  
Call Subroutine with Start Label: CLEAR

**Line#301**

label:  
comment: user comment for line #0301  
Set/Clear Flag Bit -- SET STP 011  
SET SEQ PRG-to-PLC FLAG #011 : STP 011

**Line#302**

label:  
 comment: user comment for line #0302  
 Return from Subroutine

**Line#303**

label: CALIB  
 comment: user comment for line #0303  
 Call Subroutine with Start Label: CLOSESET

**Line#304**

label:  
 comment: user comment for line #0304  
 Set Maximum Torque Limit -- TNV 016 %

**Line#305**

label:  
 comment: user comment for line #0305  
 Velocity Move -- Velocity = 1.00 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: Incremental Distance = 3.000 inch  
 Action #1 (Trig #1): Set PRG-to-PLC Flag #001  
 Action #2 (Trig #1): No Action  
 Trigger #2: PLC-to-PRG Flag #001, Logic One  
 Action #1 (Trig #2): Terminate Motion Instruction  
 Action #2 (Trig #2): No Action

**Line#306**

label:  
 comment: user comment for line #0306  
 Set/Clear Flag Bit -- SET STP 016  
 SET SEQ PRG-to-PLC FLAG #016 : STP 016

**Line#307**

label:  
 comment: user comment for line #0307  
 Time Delay: 1 seconds

**Line#308**

label:  
 comment: user comment for line #0308  
 Set/Clear Flag Bit -- CLEAR STP 001  
 CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#309**

label:  
 comment: user comment for line #0309  
 Wait for Input / Flag -- PTS 035 -- Logic 0  
 Conditional Operand: PLC-to-SEQ PRG FLAG #035 : PTS 035  
 Continue on Logic 0 (normally-closed)  
 Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#310**

label:  
 comment: user comment for line #0310  
 Set/Clear Flag Bit -- CLEAR STP 016  
 CLEAR SEQ PRG-to-PLC FLAG #016 : STP 016

**Line#311**

label:  
 comment: user comment for line #0311  
 Set Command Position = Actual -- Zero Following Error

**Line#312**

label:  
 comment: user comment for line #0312  
 Store Position to Register: PNV 025-CalibPos  
 Store Absolute ACTUAL Position

**Line#313**

label:  
 comment: user comment for line #0313  
 Inc Position Move -- Distance = -0.250 inch  
 Vel = 1.00 Acc = 400.0 Dec = 400.0  
 Trigger #1: No Trigger Event  
 Trigger #2: No Trigger Event

**Line#314**

label:  
comment: user comment for line #0314  
Wait for Input / Flag -- PTS 020 -- Logic 0  
Conditional Operand: PLC-to-SEQ PRG FLAG #020 : PTS 020  
Continue on Logic 0 (normally-closed)  
Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#315**

label: NOTORQU2  
comment: user comment for line #0315  
Return from Subroutine

**Line#316**

label: CLOSEPOS  
comment: user comment for line #0316  
Call Subroutine with Start Label: CLOSESET

**Line#317**

label:  
comment: Move to weld position  
Set Maximum Torque Limit -- TNV 017 %

**Line#318**

label:  
comment: user comment for line #0318  
Set/Clear Flag Bit -- SET STP 001  
SET SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#319**

label:  
comment: user comment for line #0319  
Velocity Move -- Velocity = 0.75 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: PLC-to-PRG Flag #001 Logic One  
Action #1 (Trig #1): Terminate Motion Instruction  
Action #2 (Trig #1): No Action  
Trigger #2: No Trigger Event

**Line#320**

label:  
comment: user comment for line #0320  
Store Position to Register: PNV 025-CalibPos  
Store Absolute ACTUAL Position

**Line#321**

label:  
comment: user comment for line #0321  
Time Delay: 0.5 seconds

**Line#322**

label:  
comment: user comment for line #0322  
Inc Position Move -- Distance = -0.500 inch  
Vel = 1.00 Acc = 25.0 Dec = 25.0  
Trigger #1: No Trigger Event  
Trigger #2: No Trigger Event

**Line#323**

label:  
comment: user comment for line #0323  
Time Delay: 0.5 seconds

**Line#324**

label:  
comment: Move to weld position  
Set Maximum Torque Limit -- TNV 018 %

**Line#325**

label:  
comment: user comment for line #0325  
Velocity Move -- Velocity = 0.75 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: PLC-to-PRG Flag #001 Logic One  
Action #1 (Trig #1): Terminate Motion Instruction  
Action #2 (Trig #1): No Action  
Trigger #2: No Trigger Event

**Line#326**

label:  
 comment: user comment for line #0326  
 Store Position to Register: PNV 026-  
 Store Absolute ACTUAL Position

**Line#327**

label:  
 comment: user comment for line #0327  
 Set/Clear Flag Bit -- CLEAR STP 001  
 CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#328**

label:  
 comment: user comment for line #0328  
 Set/Clear Flag Bit -- SET STP 015  
 SET SEQ PRG-to-PLC FLAG #015 : STP 015

**Line#329**

label:  
 comment: user comment for line #0329  
 Time Delay: 0.5 seconds

**Line#330**

label:  
 comment: user comment for line #0330  
 Wait for Input / Flag -- PTS 020 -- Logic 0  
 Conditional Operand: PLC-to-SEQ PRG FLAG #020 : PTS 020  
 Continue on Logic 0 (normally-closed)  
 Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#331**

label:  
 comment: user comment for line #0331  
 Return from Subroutine

**Line#332**

label: CLOSELIM  
 comment: user comment for line #0332  
 Call Subroutine with Start Label: CLOSESET

**Line#333**

label:  
 comment: Move to weld position  
 Set Maximum Torque Limit -- 30.0 %

**Line#334**

label:  
 comment: user comment for line #0334  
 Set/Clear Flag Bit -- SET STP 014  
 SET SEQ PRG-to-PLC FLAG #014 : STP 014

**Line#335**

label:  
 comment: user comment for line #0335  
 Set/Clear Flag Bit -- SET STP 001  
 SET SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#336**

label:  
 comment: user comment for line #0336  
 Velocity Move -- Velocity = 0.75 inch / sec  
 Acc = 250.0 Dec = 250.0  
 Trigger #1: PLC-to-PRG Flag #001 Logic One  
 Action #1 (Trig #1): Terminate Motion Instruction  
 Action #2 (Trig #1): No Action  
 Trigger #2: No Trigger Event

**Line#337**

label:  
 comment: user comment for line #0337  
 Set/Clear Flag Bit -- CLEAR STP 001  
 CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#338**

label:  
 comment: user comment for line #0338  
 Set/Clear Flag Bit -- CLEAR STP 014  
 CLEAR SEQ PRG-to-PLC FLAG #014 : STP 014

**Line#339**

label:  
comment: user comment for line #0339  
Time Delay: 0.5 seconds

**Line#340**

label:  
comment: user comment for line #0340  
Store Position to Register: PNV 027-CWLlimit  
Store Absolute ACTUAL Position

**Line#341**

label:  
comment: user comment for line #0341  
Set/Clear Flag Bit -- SET STP 015  
SET SEQ PRG-to-PLC FLAG #015 : STP 015

**Line#342**

label:  
comment: user comment for line #0342  
Wait for Input / Flag -- PTS 020 -- Logic 0  
Conditional Operand: PLC-to-SEQ PRG FLAG #020 : PTS 020  
Continue on Logic 0 (normally-closed)  
Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#343**

label:  
comment: user comment for line #0343  
Return from Subroutine

**Line#344**

label: CAPCHECK  
comment: user comment for line #0344  
Call Subroutine with Start Label: CLOSESET

**Line#345**

label:  
comment: user comment for line #0345  
Set/Clear Flag Bit -- CLEAR STP 012  
CLEAR SEQ PRG-to-PLC FLAG #012 : STP 012

**Line#346**

label:  
comment: Move to weld position  
Set Maximum Torque Limit -- 30.0 %

**Line#347**

label:  
comment: user comment for line #0347  
Set/Clear Flag Bit -- SET STP 001  
SET SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#348**

label:  
comment: user comment for line #0348  
Velocity Move -- Velocity = 0.75 inch / sec  
Acc = 250.0 Dec = 250.0  
Trigger #1: PLC-to-PRG Flag #001 Logic One  
Action #1 (Trig #1): Terminate Motion Instruction  
Action #2 (Trig #1): No Action  
Trigger #2: No Trigger Event

**Line#349**

label:  
comment: user comment for line #0349  
Set/Clear Flag Bit -- CLEAR STP 001  
CLEAR SEQ PRG-to-PLC FLAG #001 : STP 001

**Line#350**

label:  
comment: user comment for line #0350  
Position Compare - Branch Label: GOODTOGO  
Comparison: Actual Position < PNV 029

**Line#351**

label:  
comment: user comment for line #0351  
Set/Clear Flag Bit -- SET STP 012  
SET SEQ PRG-to-PLC FLAG #012 : STP 012

**Line#352**

label: GOODTOGO  
 comment: user comment for line #0352  
 Set/Clear Flag Bit -- SET STP 015  
 SET SEQ PRG-to-PLC FLAG #015 : STP 015

**Line#353**

label:  
 comment: user comment for line #0353  
 Time Delay: 0.5 seconds

**Line#354**

label:  
 comment: user comment for line #0354  
 Wait for Input / Flag -- PTS 020 -- Logic 0  
 Conditional Operand: PLC-to-SEQ PRG FLAG #020 : PTS 020  
 Continue on Logic 0 (normally-closed)  
 Do NOT Enable PLC Commanded JOG Motion while Waiting

**Line#355**

label:  
 comment: user comment for line #0355  
 Return from Subroutine

**Line#356**

label: NOTPOS  
 comment: user comment for line #0356  
 Set/Clear Flag Bit -- SET STP 013  
 SET SEQ PRG-to-PLC FLAG #013 : STP 013

**Line#357**

label:  
 comment: user comment for line #0357  
 Time Delay: 0.01 seconds

**Line#358**

label:  
 comment: user comment for line #0358  
 Set/Clear Flag Bit -- CLEAR STP 013  
 CLEAR SEQ PRG-to-PLC FLAG #013 : STP 013

**Line#359**

label:  
 comment: user comment for line #0359  
 Set/Clear Flag Bit -- SET STP 020  
 SET SEQ PRG-to-PLC FLAG #020 : STP 020

**Line#360**

label:  
 comment: user comment for line #0360  
 Return from Subroutine

**NOTES**



**TOL-O-MATIC, INC.**  
3800 County Road 116  
Hamel, MN 55340  
763.478.8000 Telephone  
763.478.8080 Fax  
<http://www.tolomatic.com>