Certificate Number Report Reference Date	UL-US-L325350-11-12019002-1 E325350-20091021 11-Dec-2020	
Issued to:	Tolomatic Inc 3800 County Road 116 Hamel, MN United States 55340-9342	
This is to certify that representative samples of	NDMM2 - Incomplete Rotating Machines and Rotating Machine Parts - Component	
	See Addendum Page for Product Designation(s).	
	Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.	
Standard(s) for Safety:	UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2018-08-07	
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information	

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bamples


Bruce Mahrenholz, Director North American Certification Program

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Date UL-US-L325350-11-12019002-1 E325350-20091021 11-Dec-2020

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
%CSW/X3 V23	Incomplete Motor Parts
%CSW/X3 V23W	Incomplete Motor Parts
%CSW/X3 V24	Incomplete Motor Parts
%CSW/X3 V24W	Incomplete Motor Parts
%CSW/X3 V43	Incomplete Motor Parts
%CSW/X3 V43W	Incomplete Motor Parts
%CSW/X3 V44	Incomplete Motor Parts
%CSW/X3 V44W	Incomplete Motor Parts
GSWA04 MV22	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV42	Incomplete Motor Parts
GSWA04 MV43	Incomplete Motor Parts
GSWA33 MV23	Incomplete Motor Parts
GSWA33 MV23WC	Incomplete Motor Parts
GSWA33 MV43	Incomplete Motor Parts
GSWA33 MV43WC	Incomplete Motor Parts
GSWA44 MV23	Incomplete Motor Parts
GSWA44 MV43	Incomplete Motor Parts
GSWA44 MV43WC	Incomplete Motor Parts
IMA22 MV21	Incomplete Motor Parts
IMA22 MV23	Incomplete Motor Parts
IMA22 MV41	Incomplete Motor Parts
IMA22 MV43	Incomplete Motor Parts
IMA33 MV21	Incomplete Motor Parts
IMA33 MV23	Incomplete Motor Parts
IMA33 MV41	Incomplete Motor Parts
IMA33 MV43	Incomplete Motor Parts
IMA44 MV23	Incomplete Motor Parts
IMA44 MV43	Incomplete Motor Parts
IMA55 MV23	Incomplete Motor Parts
IMA55 MV43	Incomplete Motor Parts
IMAS*22 MV21	Incomplete Motor Parts
IMAS*22 MV23	Incomplete Motor Parts
IMAS*22 MV41	Incomplete Motor Parts
IMAS*22 MV43	Incomplete Motor Parts
IMAS*33 MV21	Incomplete Motor Parts
IMAS*33 MV23	Incomplete Motor Parts
IMAS*33 MV41	Incomplete Motor Parts
IMAS*33 MV43	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Date UL-US-L325350-11-12019002-1 E325350-20091021 11-Dec-2020

SWA/B 3 A3	Incomplete Motor Parts
SWA/B 3 B3	Incomplete Motor Parts
SWA/B 3 B3WC	Incomplete Motor Parts
SWA/B 4 A2	Incomplete Motor Parts
SWA/B 4 A2WC	Incomplete Motor Parts
SWA/B 4 A3	Incomplete Motor Parts
SWA/B 4 A3WC	Incomplete Motor Parts
SWA/B 4 A4	Incomplete Motor Parts
SWA/B 4 A4WC	Incomplete Motor Parts
SWA/B 4 B2	Incomplete Motor Parts
SWA/B 4 B2WC	Incomplete Motor Parts
SWA/B 4 B3	Incomplete Motor Parts
SWA/B 4 B3WC	Incomplete Motor Parts
SWA/B 4 B4	Incomplete Motor Parts
SWA/B 4 B4WC	Incomplete Motor Parts

Bamely



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Date

UL-CA-L325350-31-12019002-1 E325350-20091021 11-Dec-2020

Issued to: Tolomatic Inc 3800 County Road 116 Hamel, MN United States 55340-9342

This is to certify that representative samples of

NDMM8 - Incomplete Rotating Machines and Rotating Machine Parts Certified for Canada - Component See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:	CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

4 mally


Bruce Mahrenholz, Director North American Certification Program

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Date UL-CA-L325350-31-12019002-1 E325350-20091021 11-Dec-2020

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
%CSW/X3 V23	Incomplete Motor Parts
%CSW/X3 V23W	Incomplete Motor Parts
%CSW/X3 V24	Incomplete Motor Parts
%CSW/X3 V24W	Incomplete Motor Parts
%CSW/X3 V43	Incomplete Motor Parts
%CSW/X3 V43W	Incomplete Motor Parts
%CSW/X3 V44	Incomplete Motor Parts
%CSW/X3 V44W	Incomplete Motor Parts
GSWA04 MV22	Incomplete Motor Parts
GSWA04 MV23	Incomplete Motor Parts
GSWA04 MV42	Incomplete Motor Parts
GSWA04 MV43	Incomplete Motor Parts
GSWA33 MV23	Incomplete Motor Parts
GSWA33 MV23WC	Incomplete Motor Parts
GSWA33 MV43	Incomplete Motor Parts
GSWA33 MV43WC	Incomplete Motor Parts
GSWA44 MV23	Incomplete Motor Parts
GSWA44 MV43	Incomplete Motor Parts
GSWA44 MV43WC	Incomplete Motor Parts
IMA22 MV21	Incomplete Motor Parts
IMA22 MV21	Incomplete Motor Parts
IMA22 MV20	Incomplete Motor Parts
IMA22 MV41	Incomplete Motor Parts
IMA33 MV21	Incomplete Motor Parts
IMA33 MV23	Incomplete Motor Parts
IMA33 MV23	Incomplete Motor Parts
IMA33 MV41	Incomplete Motor Parts
IMA33 MV43 IMA44 MV23	Incomplete Motor Parts
IMA44 MV23	Incomplete Motor Parts
IMA44 MV43	Incomplete Motor Parts
IMA55 MV23	Incomplete Motor Parts
IMAS*22 MV21	Incomplete Motor Parts
IMAS*22 MV23	Incomplete Motor Parts
IMAS*22 MV41	Incomplete Motor Parts
IMAS*22 MV43	Incomplete Motor Parts
IMAS*33 MV21	Incomplete Motor Parts
IMAS*33 MV23	Incomplete Motor Parts
IMAS*33 MV41	Incomplete Motor Parts
IMAS*33 MV43	Incomplete Motor Parts



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

Certificate Number Report Reference Date UL-CA-L325350-31-12019002-1 E325350-20091021 11-Dec-2020

SWA/B 3 A3	Incomplete Motor Parts
SWA/B 3 B3	Incomplete Motor Parts
SWA/B 3 B3WC	Incomplete Motor Parts
SWA/B 4 A2	Incomplete Motor Parts
SWA/B 4 A2WC	Incomplete Motor Parts
SWA/B 4 A3	Incomplete Motor Parts
SWA/B 4 A3WC	Incomplete Motor Parts
SWA/B 4 A4	Incomplete Motor Parts
SWA/B 4 A4WC	Incomplete Motor Parts
SWA/B 4 B2	Incomplete Motor Parts
SWA/B 4 B2WC	Incomplete Motor Parts
SWA/B 4 B3	Incomplete Motor Parts
SWA/B 4 B3WC	Incomplete Motor Parts
SWA/B 4 B4	Incomplete Motor Parts
SWA/B 4 B4WC	Incomplete Motor Parts

Bamely



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/