


# GSWA101 Hex Thrust Rod Grease Access Hole Orientation



## Instructions:

The wiper scraper kit is pre-drilled at Tolomatic. It is shipped with 2 wires to keep the holes of the wiper and scraper aligned.

The drilling process is done at the angle shown in the above graphic to allow for greasing of the wiper via needle and grease gun while the actuator remains installed in the application.

Remove wires before assembly. Keep the holes of the wiper & scraper aligned when installing. Use the above graphic for proper assembly orientation of the components to insure the correct drill angle orientation relative to the motor and feedback connectors on the assembly.



3800 County Road 116, Hamel, MN 55340

<http://www.Tolomatic.com> • Email: [Help@Tolomatic.com](mailto:Help@Tolomatic.com)

Phone: (763) 478-8000 • Fax: (763) 478-8080 • Toll Free: 1-800-328-2174



Information furnished is believed to be accurate and reliable. However, Tolomatic assumes no responsibility for its use or for any errors that may appear in this document. Tolomatic reserves the right to change the design or operation of the equipment described herein and any associated motion products without notice. Information in this document is subject to change without notice.